


PACKING CUTTERS



Guillotine Cutter



- Packing rings can be cut either with a 45° angle, or with a so called butt cut.
- Usually 45° cuts are for valve applications and butt cuts for pumps, however many people prefer the 45° cut for their pumps. It is purely a matter of choice.
- When fitting the rings, ensure that the cuts are staggered at 90° intervals in the opposite direction of the shaft rotation.
- Eliminate expensive time and material waste from trial-and-error fitting, with diameter/circumference scales. There are two sizes: a maximum shaft size of 4" or 10".
- Easily cuts all packing including: copper sheathed and wire core packing to 1" diameter at 45° or butt angles.

Hand Cutter

